







# CABLAGE VEGA-MARK3 Ibutton v1.1



SW1 / SW2 / SW3 / SW4 ON = RAZ USINE +AUTOTEST  
 SW3 ON (SEUL) = MARCHÉ FORCÉE  
 SW4 ON = Mode DEGRADE

CABLAGE VEGA MARK 3 / IBUTTON			
1.1	DataComSys	12/03/20	PL